

HABS  
PR,  
6-PONCE,  
2-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Armstrong, Carlos, Casa  
9 Plaza Munoz Rivera  
Ponce  
Puerto Rico

HABS No. PR-74

Jack E. Boucher, photographer, August 1977

- PR-74-1 East elevation (main)
- PR-74-2 East elevation from northeast
- PR-74-3 Detail showing wrought iron gate, north end of east elevation
- PR-74-4 Detail showing windows, east elevation
- PR-74-5 East entrance from northeast
- PR-74-6 Detail showing east entrance
- PR-74-7 Detail showing caryatid east entrance
- PR-74-8 Interior, east front door from entrance hall
- PR-74-9 Interior, detail showing stained glass windows, east door
- PR-74-10 Interior, detail showing staircase
- PR-74-11 Interior, east parlor
- PR-74-12 Interior, general view of parlor
- PR-74-13 Interior, detail showing parlor ceiling and doorway screen
- PR-74-14 Interior, dining room showing painted wainscoting
- PR-74-15 Interior, general view of kitchen
- PR-74-16 Interior, detail showing water cooler
- PR-74-17 Interior, detail showing water vessel

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

ADDENDUM TO  
CASA CARLOS ARMSTRONG  
9 Plaza Munoz Rivera  
Ponce  
Municipality of Ponce  
Puerto Rico

HABS No. PR-74  
(p. 2)

HABS  
PR  
6-PONCE  
2-

PR-74-1 through PR-71-17 were previously transmitted to the Library of Congress.

### INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, August 1977

PR-74-18 (CT)	EAST ELEVATION (MAIN)
PR-74-19 (CT)	EAST ENTRANCE FROM NORTHEAST
PR-74-20 (CT)	DETAIL SHOWING EAST ENTRANCE
PR-74-21 (CT)	INTERIOR, DETAIL SHOWING STAINED GLASS WINDOWS, EAST DOOR